



Shielded Z-MAX® Outlet Installation Instructions




Tools Required

- Ⓐ Small Flathead Screwdriver
- Ⓑ Diagonal Cutter (CI-CUTTER)
- Ⓒ Jacket Prep Tool (CPT-RGTP)
- Ⓓ Termination Tool (Z-TOOL)
- Ⓔ Permanent Marker




1A


! Category 6A Solid F/UTP Shown - See back page for additional cable options




1B




1C



2












3


















4

Shielded Z-MAX® Outlet Installation Instructions



Shielded Z-MAX® Outlet Installation Instructions




! NOTE (steps 20-21): Reterminations are not recommended with 22 AWG shielded cables.

Shielded Z-MAX® Outlet Installation Instructions


Alternate Step 1. cable prep for other cable types

S/FTP Stranded




Go To Step 2

S/FTP Solid and F/FTP Solid




Go To Step 2

F/UTP (5e) Stranded & Solid



Go To Step 2

U/FTP Solid



Go To Step 2

To assist safe installations, comply with the following:

- Use caution when installing or modifying telecommunications circuits.
- Never touch uninsulated wire terminals unless the circuit has been disconnected.
- Never install this device in a wet location.
- Never install wiring during a lightning storm.

Lors de l'installation, respectez les consignes de sécurité suivantes:

- Utiliser avec prudence lors de l'installation ou de la modification circuits de télécommunications.
- Ne jamais toucher les bornes de fil métallique non isolés sauf si le circuit a été débranché.
- Ne jamais installer cet appareil dans un endroit humide.
- Ne jamais installer pendant un orage.

To ensure you have the latest revision to this document, please visit: <http://www.siemon.com/us>