



INDUSTRIAL TESTING LABORATORY

CERTIFICATE OF COMPLIANCE

Based on Report: 180507-01C

Report Date: 04 June 2018

TEST REPORT

Test Component: SISTEMAS Y SERVICIOS DE COMUNICACION S.A. DE C.V.
X13 8-LED Red Directional Warning Lamp
SAE W-1 and SAE WS3-1(80)
With 8 Flash Patterns

Submitted by: 3rd Party

Test Laboratory: Calcoast - ITL
San Leandro, CA 94577

Samples Tested: Three (3) submitted 07 May 2018

SUMMARY

Specifications: SAE J595 MAR2014 and SAE J845 JUN2013

Photometric Test -

- SAE J595 MAR2014 Class 1 Red - SAE W-1 in all FPsPassed
- SAE J845 JUN2013 Class 1 Red - SAE WS3-1(80) in all FPsPassed

- Flash Characteristics - Flash Patterns 1-8.....Passed
- Environmental (Flash Rate) Tests - SAE J595 and SAE J845.....Passed
- Mechanical Tests - SAE J575 AUG15
(Vibration, Moisture, Dust, Corrosion and Warpage)Passed
- Color Test - SAE J578 MAR16.....Passed
- Lens Material - SAE J576 AUG17.....Unknown

Additional Tests

- Chemical Resistance Test - SAE J575 AUG15 4.15.....Passed

Signature of Responsible Laboratory Official:

Mark A. Evans
Laboratory Director

PHOTOGRAPH SHEET

Device Name: SISTEMAS Y SERVICIOS DE COMUNICACION S.A. DE C.V.
X13 8-LED Red Directional Warning Lamp

